

ERRATUM

Vibration Control of Active Structures (3rd Edition)

November 22, 2011

In chapter 6, Figure 6.5 has been misplaced. The figure should be as follows:




Figure 6.5: Two-mass problem, root locus plot for the non-collocated control with a lead compensator.